



DATE: 2023-08-10

MODEL: SR3 XXR

LAMINOVA – HEAT EXCHANGER HR0092


PRIORITY – LOW (INFORMATION)

In the event of an Engine or GDU Failure where swarf contamination could occur it is important to flush or replace oil lines and replace related Laminova core.

Both of the cores and a rebuild kit containing all gaskets and seals are available from Radical.

Laminova
HR0092

Rebuild Kit
HR0093



Engine Core Long
HR0095

GDU Core Short
HR0094