



DATE: 2022-05-10

MODEL: ALL MODELS

SUBJECT: BRAKE PAD RETAINING BOLTS

PRIORITY – HIGH (ACTION)

It has been noticed that on a small number of new car inspection PDIs that the brake pad retaining bolt has become loose. Dealers are reminded that all cars should be thoroughly spanner checked as part of the post transit checks.

The bolt should be fitted with two locking serrated washers.

Additional processes have been implemented at the factory to ensure this does not re-occur on future car builds.



For parts supply please contact: stores@radicalsportscars.com

For technical enquiries please contact: technical@radicalsportscars.com

Technical Department
Radical Sportscars

Email: technical@radicalsportscars.com



RADICAL