



DATE: 2022-07-19

MODEL: SR8/SR10

SUBJECT: TJ0023 CV BOOT - QUALITY

***PRIORITY – HIGH (ACTION)***

---

It has been found that some TJ0023 CV boots have manufacturing defects that can cause premature failure.

Customer are advised to check any stock they have and notify Radical if any faulty parts are found.



TJ0023 - Manufacturing fault

For parts supply please contact: [stores@radicalsportscars.com](mailto:stores@radicalsportscars.com)

For technical enquiries please contact: [technical@radicalsportscars.com](mailto:technical@radicalsportscars.com)

Technical Department  
Radical Sportscars

Email: [technical@radicalsportscars.com](mailto:technical@radicalsportscars.com)



**RADICAL**