




DATE: 2023-04-13

MODEL: SR3XX

STEERING WHEEL DISPLAY ISSUES

PRIORITY – MEDIUM (MONITOR) SOME AFFECTED VEHICLES

A bug has been found in the Aim software which can cause the voltage and oil pressure value to be displayed incorrectly on the steering wheel display. See below example:



To rectify this issue, please load PDM32-SR3-XX-v14 config.

This will be supplied upon request from

technical@radicalmotorsport.com

Technical Department
Radical Motorsport

Mobile: +44 (0)7876 146854
Tel: +44 (0)1733 331616 ext. 263
Email: technical@radicalmotorsport.com



RADICAL